CMS R8573 - Maintenance

- Deployment: Enabled persist config by default for Mako profiles created before 2019.
- Firmware: Added the ability to suspend automatic pushing out of firmware updates for a specific firmware stream.
 Updates will still occur on demand, and upon Mako device reboot where applicable.
- Merchant PCI: Fixed reporting issue with Vulnerability Scan results spanning multiple LANs.
- Reports: Various small quality of life improvements.

CMS R8570 - New Features and Improvements

PCI DSS v4.0

We've updated the SAQ generation service to support the PCI DSS v4.0 SAQ forms.

Reports Update

We've updated the look and feel of the various Makospecific reports, including usage and Mako Guardian reports.

CMS R8570 - Maintenance

- API: Fixed issue with low rate limits on various API calls.
- Hotspot: Fixed issue with Hotspots not working when attached to a 4-digit VLAN ID.
- Login: Various small quality of life improvements and fixes.
- Merchant PCI: Various small quality of life improvements and fixes.
- Search: Fixed issue selecting a Site in the universal search screen.
- Site Diagram: Fixed issue exporting the site network diagram in Firefox.
- SSO: Added warning when SSO is enabled but no providers configured.
- VLAN: Fixed issue with saving VLAN IGMP settings.

CMS R8572 - Maintenance

- Deployment: Fixed inability to move sites introduced in R8570.
- Merchant PCI: Various small quality of life improvements.
- Provisioning: Fixed issue with incorrectly rejected names.
- Reports: Various small quality of life improvements.
- Switch Config: Fixed issue with incomplete list of guest VLANs for 802.1X.

Have a suggestion to improve your experience with the Mako System? We'd love to hear from you! support@makonetworks.com



Changelog CMS R8573

Please consider the environment before printing this document.