



CMS R7920 - Maintenance

- **Diagnostics:** Added routing engine diagnostics to Mako 6600 series.
- **Enterprise Templates:** Added RULE_LOCATION option to avoid creating redundant rules in certain scenarios.
- **Failover:** Updated Mako HA failover to allow some LANs to not share the same subnets across both Makos.
- **Network:** Changed default LAN subnet from 192.168.1.x to 192.168.20.x.
- **VPN Cloud:** Improved performance of VPN Cloud listing page for a company.

Have a suggestion to improve your experience with the Mako System?
We'd love to hear from you! support@makonetworks.com



Changelog
CMS R7920

Please consider the environment before printing this document.