

Switch FSW1241 - Maintenance

- Management: Fixed rare issue with losing connection to management system.

Switch FSW1240 - Maintenance

- Logs: Remove STP logs when STP is not enabled.
- PoE: Fixed issue with PoE not working after a factory reset.
- VoIP VLAN: Added support for VoIP VLAN configuration.

Have a suggestion to improve your experience with the Mako System?
We'd love to hear from you! support@makonetworks.com

Please consider the environment before printing this document.

