CPE F6320 - Maintenance

- Firewall: Fixed issue with Service Groups unable to include ESP.

- Health Monitors: Fixed issue with diagnostic output not displaying unresolvable hosts correctly.

- Health Monitors: Improved wording of Health Monitor up/down syslogs.

- MakoScope: Added rate limiting to the MakoScope (1 request/second).

- QoS: Fixed issue with inbound QoS introduced in F6300 on Mako 7000 series devices and Cloud Mako device.

- VPN Cloud: Added more diagnostic information when concentrators are overloaded.

- VPN Cloud: Fixed issue with VPN Cloud restarting after a name change.

- VPN Cloud: Improved upstream NAT compatibility between two remote Mako devices when the Suggest Temporary Connections option is enabled.

- VPN Cloud: Improved handling of concurrent reconnections from large numbers of Mako devices.

Have a suggestion to improve your experience with the Mako System?
We'd love to hear from you! support@makonetworks.com

Mako NETWORKS

Changelog
CPE F6320

Please consider the environment before printing this document.