CPE F6550 - Features and Improvements

- **Mako Periscope Support**
  We've added enhanced support for the Mako Periscope service. We strongly recommend updating to F6550 or newer for the best, most responsive and secure experience using Mako Periscope. Earlier firmware versions have limited support for the service.

CPE F6550 - Maintenance

- Cellular: Fixed issue wth 5G signal strength reporting on Mako 5600 series hardware.

- Monitoring: Fixed rare stability issue when using ICMP ping health monitors.

CPE F6550 - Known Issues

- Mako 4550: In order to upgrade to F6540 or newer, the Mako device must first be running F6513 or newer. Please contact Mako Support if you need to upgrade a Mako 4550 running firmware older than F6513.

- Mako 4000 and 5000 series on firmware earlier than F6540: The MAC address used by the Mako device when requesting a DHCP lease may have changed away from the MAC address used in earlier firmware versions. Please update any applicable static DHCP leases as required to use the new MAC address.

Have a suggestion to improve your experience with the Mako System?
We'd love to hear from you! support@makonetworks.com

Mako NETWORKS

Changelog
CPE F6550

Please consider the environment before printing this document.