



CPE F6411 - Maintenance

- Diagnostics: Added SFP status diagnostic for Security Gateways that support SFP modules.
- SFP: Fixed issue with SFP module support on Mako 6600 series.
- Speed Test: Fixed issue with speed test server port not customisable.

Have a suggestion to improve your experience with the Mako System?
We'd love to hear from you! support@makonetworks.com



Changelog
CPE F6411

Please consider the environment before printing this document.

