

### CPE F6512 - Maintenance

- IPsec: Fixed issue with fast DPD timeouts on IKEv2 connections taking longer than expected to trigger.

### CPE F6511 - Maintenance

- VPN Cloud: Added support for local breakout routes when in zero-route mode.

### CPE F6510 - Maintenance

- Cellular: Improved Verizon support for Mako 5600 devices.
- Internet: Fixed issue with health tests not working on WAN 5 and WAN 6.
- Wi-Fi: Increased SSID limit to 16 for Mako 4000-series and Mako 5000-series, and to 8 for Mako 6600-series.
- Wi-Fi: Improved Wi-Fi compatibility and stability on Mako 4000-series.

Have a suggestion to improve your experience with the Mako System?  
We'd love to hear from you! [support@makonetworks.com](mailto:support@makonetworks.com)

Please consider the environment before printing this document.

