

### CPE F6513 - Maintenance

- Cellular: Improved handling of Verizon SIMs on Mako 5600 and Mako 6600 series hardware.
- Firmware Update: Improved handling of future firmware updates for Mako 4550 series hardware.
- Health Monitors: Now sends Up/Down messages for all monitored hosts initial state when the Mako Device starts up or is rebooted.
- Mako Guardian: Now blocks QUIC by default when HTTPS filtering is enabled.
- Speed Tests: Fixed issue with schedule changes not being actioned.
- Verifone: Now detects Verifone Commander version for compatibility.
- Wi-Fi: Enabled Multicast-to-Unicast as default for Mako 4600 series hardware.

### CPE F6512 - Maintenance

- IPsec: Fixed issue with fast DPD timeouts on IKEv2 connections taking longer than expected to trigger.

### CPE F6511 - Maintenance

- VPN Cloud: Added support for local breakout routes when in zero-route mode.

### CPE F6510 - Maintenance

- Cellular: Improved Verizon support for Mako 5600 devices.
- Internet: Fixed issue with health tests not working on WAN 5 and WAN 6.
- Wi-Fi: Increased SSID limit to 16 for Mako 4000-series and Mako 5000-series, and to 8 for Mako 6600-series.
- Wi-Fi: Improved Wi-Fi compatibility and stability on Mako 4000-series.

