



## CPE F6113 - Maintenance

- Cellular: Improved compatibility with US cellular carriers.

## CPE F6111 - Maintenance

- Firewall: Fixed issue with Intranet traffic during WAN failover events.

## CPE F6110 - Maintenance

- |  |  |
|--|--|
| <ul style="list-style-type: none"><li>● Cellular: Fixed issues with Mako 6600 series cellular configurations.</li><li>● Firewall: Fixed issue related to TCP SACK.</li><li>● Guardian: Fixed issue with invalid regular expressions.</li><li>● Hardware: Added support for Mako 8600 series.</li></ul> | <ul style="list-style-type: none"><li>● Hardware: Fixed issue with temperature sensor readings on Mako 6600 series.</li><li>● VPN: Upgrade IPsec engine to latest version.</li><li>● VPN Cloud: Fixed issue with Seamless Voice on Mako 6600 series.</li></ul> |
|--|--|

Have a suggestion to improve your experience with the Mako System?  
We'd love to hear from you! [support@makonetworks.com](mailto:support@makonetworks.com)



Changelog  
CPE F6113

Please consider the environment before printing this document.