

CPE F6250 - Features and Improvements

- | | |
|---|--|
| <ul style="list-style-type: none">● DSL: Added PPPoA support for DSL on the Mako 6600 series.● Hotspot: Added Hotspot support to Mako 4600 series. | <ul style="list-style-type: none">● IPsec: Added ability to run IPsec on any WAN or LAN, not just the default route.● SNMP: Added SNMP support to Mako 4600 series. |
|---|--|

CPE F6250 - Maintenance

- | | |
|---|---|
| <ul style="list-style-type: none">● Diagnostics: Fixed issue with Bridge Status diagnostics on Mako 4600, 6600, 7600, 8600 series.● Diagnostics: Fixed issue with MakoScope not showing VLANs for access points.● DNS: Fixed issue with the Mako's internal DNS client lookups not working over a VPN.● DSL: Added ability to override interface MAC address for DSL on Mako 6600 series.● Firewall: Fixed issue with responding to ARP queries sent to the wrong interface.● Hotspot: Fixed issue with Hotspot becoming unresponsive under certain circumstances.● Hotspot: Fixed issue with Hotspot unable to register under clients certain circumstances. | <ul style="list-style-type: none">● Hotspot: Fixed issue with Hotspot configuration change not being applied under certain circumstances.● IDS: Fixed IDS logs not being included in remote syslogs.● Internet: Fixed issue with DHCP lease renewal failing in certain situations.● SFP: Fixed issue with bridging a SFP port to a LAN on Mako 6600 series.● SNMP: Fixed issue with cellular interface status on 6600 series.● VPN Cloud: Fixed issue where watchdog did not restart the VPN Cloud process on remote peers when it should.● Wi-Fi: Fixed compatibility issue with IoT (ESP 8266) devices connecting to Mako 4600 series Wi-Fi networks.● Wi-Fi: Fixed issue with a brief connectivity loss when adding VLAN interfaces on access points. |
|---|---|