

CPE F6310 - Maintenance

- Cellular: Fixed issue with cellular firmware updates not starting on Mako 6600 series.
- Cellular: Fixed issue with cellular link recovery on Mako 6600 series.
- IPsec: Fixed issue with missing routes introduced in F6300.
- IPsec: Fixed issue with SNAT tunnels introduced in F6300.
- VPN Cloud: Fixed memory leak with very long running connections.
- VPN Cloud: Reduced number of configuration changes that necessitate a VPN Cloud restart.

Have a suggestion to improve your experience with the Mako System?
We'd love to hear from you! support@makonetworks.com

Please consider the environment before printing this document.