

### Switch FSW1237 - Maintenance

- Logs: Fixed issue where logs stop uploading after a long uptime.
- PoE: Added ability to specify port PoE priority and limit.

### Switch FSW1236 - Features and Enhancements

- Diagnostics: Fixed issue with incorrect port uptime statistics on ports with PoE.
- Link Aggregation: Added support for LACP.
- STP: Added support for disabling STP on a per-port basis.
- System: Fixed issue with communicating with the Mako CMS during specific conditions.

### Switch FSW1235 - Features and Enhancements

- IGMP: Added support for IGMP.

### Switch FSW1230 - Features and Improvements

- STP: Enhanced diagnostics with more STP information.

Have a suggestion to improve your experience with the Mako System?  
We'd love to hear from you! [support@makonetworks.com](mailto:support@makonetworks.com)

Please consider the environment before printing this document.

