# Changelog Switch FSW1245

Improvements for Mako's Managed Switches

## Switch FSW1245 - Maintenance

 PoE: Fixed issue with PoE not working after a firmware downgrade.

# Switch FSW1242 - Features and Improvements

 Management: Added optional suppport for a tagged VLAN as the management interface.

#### Switch FSW1241 - Maintenance

 Management: Fixed rare issue with losing connection to management system.

## Switch FSW1240 - Maintenance

- Logs: Remove STP logs when STP is not enabled.
- PoE: Fixed issue with PoE not working after a factory reset.
- VoIP VLAN: Added support for VoIP VLAN configuration.

Have a suggestion to improve your experience with the Mako System?

We'd love to hear from you! support@makonetworks.com



Changelog Switch FSW1245

Please consider the environment before printing this document.