



Changelog Switch FSW1250

Improvements for Mako's
Managed Switches

Switch FSW1250 - Features and Improvements

- ACLs: Added support for OUI-based MAC address filtering.

Switch FSW1250 - Maintenance

- | | |
|---|--|
| <ul style="list-style-type: none">● Diagnostics: Added support for remotely rebooting the switch.● Hardware: Improved support for Mako 1124 series managed switches. | <ul style="list-style-type: none">● NTP: Fixed issue with system time drifting when NTP is blocked upstream.● Ports: Added support for per-port flow control.● STP: Removed erroneous error log when LAG is enabled.● System: Reduced memory usage. |
|---|--|

Have a suggestion to improve your experience with the Mako System?
We'd love to hear from you! support@makonetworks.com



Changelog
Switch FSW1250

Please consider the environment before printing this document.

