



Changelog Switch FSW1257

Improvements for Mako's
Managed Switches

Switch FSW1257 - Maintenance

- Bootloader: Fixed issue with bootloader introduced in FSW1255.
- Firmware: Improved reliability of firmware update process.

Switch FSW1257 - Known Issues

- Downgrades: Once upgraded to FSW1257, downgrading to earlier versions of switch firmware is not supported.

Have a suggestion to improve your experience with the Mako System?
We'd love to hear from you! support@makonetworks.com



Changelog
Switch FSW1257

Please consider the environment before printing this document.

