



Changelog Switch FSW1256

Improvements for Mako's
Managed Switches

Switch FSW1256 - Maintenance

- MAC ACL: Improved support for OUI-based ACLs.
- PoE: Upgraded PoE firmware.

Switch FSW1256 - Known Issues

- Downgrades: Once upgraded to FSW1256, downgrading to earlier versions of switch firmware is not supported.

Have a suggestion to improve your experience with the Mako System?
We'd love to hear from you! support@makonetworks.com



Changelog
Switch FSW1256

Please consider the environment before printing this document.